



**TIGRIS Aquatic Services LLC**  
2165 Mount Bethel Highway  
Unit 5  
Mount Bethel, Pennsylvania 18343  
Tel: 888-243-0891

|                                                                                                             |                                                                                                                                                                                                  |
|-------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Customer:</b> Colony Lakes Home Owners Association                                                       | <b>Work Order:</b> 31087685                                                                                                                                                                      |
| 328 Jennings Rd<br>Manahawkin, New Jersey 08050<br><b>Contact:</b> John MacNeil<br><b>Phone:</b> 6092901612 | <b>Lake/Pond/Wetland/Terrestrial Treatment Service</b><br><b>Technician:</b> Jeff Horn<br><b>License #:</b><br><b>Date of Service:</b> 4/23/25<br><b>Start Time:</b> 11:00 <b>End Time:</b> 2:15 |

#### SITE "Colony Lakes - Timber Lake"

**Comments:**

At this time the lake supports shoreline cattail, and phragmites scattered around the shoreline. Observed sparse amounts of benthic filamentous algae. Lake looks good.

| Water Level | Aesthetic Appearance | Water Appearance |
|-------------|----------------------|------------------|
| Full Pool   | Good                 | Clear            |

| Aquatic Vegetation Identified               | Extent of Aquatic Vegetation |
|---------------------------------------------|------------------------------|
| Filamentous Algae<br>Cattails<br>Phragmites | Spotty                       |

| Method of Application |
|-----------------------|
| Airboat               |

| DO (mg/l) | Secchi Depth (Feet) | pH (SU) | Water Temp (°F) | Alkalinity (mg/l) | Hardness (mg/l) |
|-----------|---------------------|---------|-----------------|-------------------|-----------------|
| 9.50      | 8                   | 7       | 64.76           | 40                | 40              |

| Product Used | EPA # |
|--------------|-------|
| N/A          | N/A   |

#### SITE "Colony Lakes - Timber Lake"

**Comments:**

Observed shoreline cattail and phragmites scattered around the shoreline. Sparse scattered benthic filamentous algae. There was a slight biofilm on the surface windblown to the north end of the lake. Lakeloks good.

| Water Level | Aesthetic Appearance | Water Appearance |
|-------------|----------------------|------------------|
| Full Pool   | Good                 | Clear            |

| Aquatic Vegetation Identified               | Extent of Aquatic Vegetation |
|---------------------------------------------|------------------------------|
| Filamentous Algae<br>Cattails<br>Phragmites | Spotty                       |

| Method of Application |
|-----------------------|
| Airboat               |

| DO (mg/l)    | Secchi Depth (Feet) | pH (SU) | Water Temp (°F) | Alkalinity (mg/l) | Hardness (mg/l) |
|--------------|---------------------|---------|-----------------|-------------------|-----------------|
| 10.58        | 7                   | 7       | 64.22           | 40                | 60              |
| Product Used |                     | EPA #   |                 |                   |                 |
| N/A          |                     | N/A     |                 |                   |                 |

*Thank you for your business!*

