



TIGRIS Aquatic Services LLC
1 Shielding Way
Delaware Water Gap, Pennsylvania 18327
Tel: 888-243-0891

Customer: Colony Lakes Home Owners Association

328 Jennings Rd
Manahawkin, New Jersey 08050
Contact: John MacNeil
Phone: 6092901612

Work Order: 31087687

Lake/Pond/Wetland/Terrestrial Treatment Service

Technician: Jeff Horn

License #:

Date of Service: 5/29/25

SITE "Colony Lakes - Timber Lake"

Comments:

The lake supports dense beds of Nitella scattered on the bottom of the basin well below the surface. Sparse to moderate benthic algae scattered along the shoreline. Observed less than one dozen plants of bladderwort. Shoreline phragmites. Water samples were collected for lab analysis. Lake looks good

Water Level	Aesthetic Appearance	Water Appearance
Full Pool	Good	Clear

Aquatic Vegetation Identified	Extent of Aquatic Vegetation
Nitella Phragmites Bladderwort	Trace

Method of Application
Airboat

DO (mg/l)	Secchi Depth (Feet)	pH (SU)	Water Temp (°F)	Alkalinity (mg/l)	Hardness (mg/l)
8.35	6.5	7	66.2	40	60

Product Used	EPA #
N/A	N/A

SITE "Colony Lakes - Colony Lake"

Comments:

The lake basin supports dense patches of Nitella scattered throughout the basin well below the surface. Trace to moderate amounts of benthic algae scattered around the shoreline. Shoreline line phragmites. Water samples collected for lab analysis. Lake looks good.

Water Level	Aesthetic Appearance	Water Appearance
Full Pool	Good	Clear

Aquatic Vegetation Identified	Extent of Aquatic Vegetation
Nitella Phragmites	Heavy

Method of Application
Airboat

DO (mg/l)	Secchi Depth (Feet)	pH (SU)	Water Temp (°F)	Alkalinity (mg/l)	Hardness (mg/l)
9.1	6	7	66.02	40	40
Product Used		EPA #			
N/A		N/A			

Thank you for your business!

